



Pond Guru Fort Myers

P.O. Box 3439,
North Fort Myers, FL 33918,
(239) 997-8872

Service Report

REP-411

Contact Details

Company	:	Livingston Lakes Condo Association
Contact	:	Sarah Mackedanz
Service Address	:	15090 Palmer Lake Circle Naples, Florida 34109
Email	:	committee@livingstonlakescondo.com

Service Details

	:	WO374
Service Summary	:	Lake Maintenance
Technician Involved	:	Steve Willis CM500399
Scheduled Start Time	:	Jul 02, 2026 11:30 AM
Checked in with	:	
Trash Removed	:	Yes
Next Service Appointment	:	4+ Weeks
Equipment Used	:	Backpack, Buggy

Water / Weather Conditions

Water Level	:	Low
Water Clarity	:	Normal
Weather	:	Overcast
Wind	:	0-5 mph

Flora / Fauna Notes

Wildlife Present	:	Birds, Fish
Bird Type	:	Wading Bird
Fish Type	:	Bass, Bluegill
Reptile Type	:	
Beneficial Plants	:	Arrowhead, Bacopa, Duck Potato, Golden Canna, Spikerush
Other Beneficial Plants	:	

Erosion Report

Erosion Severity	:	None Present
Erosion Repair Recommendations	:	

Attachments



Jobsheet Details

Details/AT0188

Job Sheet Name : AT0188

Photos :

Vegetation Treated

Type	Name	Severity	Lakes Treated	Comments
Grass/Brush	Torpedoglass	Present, spotty, low amounts	All Lakes	
Grass/Brush	Dogfennel	Present, spotty, low amounts	All	
Grass/Brush	Other	Present, spotty, low amounts	All	Vines